



Errata

NFPA 13

Standard for the Installation of Sprinkler Systems

2016 Edition

Reference: Tables 19.1.2.1.3(a) and (b)

Errata No: 13-16-4

The Technical Committee on Sprinkler System Discharge and the Correlating Committee on Automatic Sprinkler Systems notes the following error in the 2016 edition of NFPA 13, *Standard for the Installation of Sprinkler Systems*.

1. In the second column heading in both Tables 19.1.2.1.3(a) and (b), add missing words “Clearance to” before “Ceiling” as shown below:

| Storage Height (ft) | Clearance to Ceiling (ft) | Closed Array Banded or Unbanded | Standards |
|---------------------|---------------------------|---------------------------------|-----------|
| | | | Banded |
| 10 | ≤5 | 0.3/2000 | 0.3/2000 |
| 10 | >5 | 0.3/2000 | 0.3/2000 |
| 15 | ≤5 | 0.3/2000 | 0.3/2000 |
| 15 | >5 | 0.3/2000 | 0.3/2000 |
| 20 | ≤5 | 0.3/2000 | 0.3/2000 |

| Storage Height (m) | Clearance to Ceiling (m) | Closed Array Banded or Unbanded | Standards |
|--------------------|--------------------------|---------------------------------|-----------|
| | | | Banded |
| 3 | ≤1.5 | 12.2/186 | 12.2/18 |
| 3 | >1.5 | 12.2/186 | 12.2/18 |
| 4.6 | ≤1.5 | 12.2/186 | 12.2/18 |
| 4.6 | >1.5 | 12.2/186 | 12.2/18 |
| 6.1 | <1.5 | 12.2/186 | 12.2/18 |

Issue Date: May 24, 2017

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/docinfo)

Copyright © 2017 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION