



## Errata

# NFPA 13

## *Standard for the Installation of Sprinkler Systems*


### 2016 Edition, First Printing

**Reference:** Figure 15.2.2.1

**Errata No:** 13-16-3

The Technical Committee on Sprinkler System Discharge and the Correlating Committee on Automatic Sprinkler Systems notes the following error in the First Printing only of the 2016 edition of NFPA 13, *Standard for the Installation of Sprinkler Systems*.

1. In Figure 15.2.2.1, correct the reference from Table 15.2.6(a) to Table 15.2.2.5(a) in eight places.



Note: Cartons that contain Group A plastic material are permitted to be treated as Class IV commodities under the following conditions:

- (1) There are multiple layers of corrugation or equivalent outer material that would significantly delay fire involvement of the Group A plastic.
- (2) The amount and arrangement of Group A plastic material within an ordinary carton would not be expected to significantly increase the fire hazard.

FIGURE 15.2.2.1 Decision Tree.

Issue Date: February 24, 2017

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see [www.nfpa.org/docinfo](http://www.nfpa.org/docinfo))

Copyright © 2017 All Rights Reserved  
NATIONAL FIRE PROTECTION ASSOCIATION